

Subject: Part 70 Compliance Certification Report due April 1, 2002

Your facility is currently operating under your Part 70 Operating Permit issued by the Air and Radiation Management Administration (ARMA). This permit requires an annual Compliance Certification due by April 1 each year. This year we are requiring that a new ARMA form and the federal Compliance Certification forms be used. Although the federal forms were developed for the federal Part 71 Permits, ARMA is using these forms for Part 70 facilities as well. The ARMA form is to be used for certifying plant-wide conditions (Section III of your Part 70 Permit) and the federal forms are to be used for certifying plant-specific conditions (Section IV of your Part 70 Permit).

Regarding the federal forms, please note that sections A and B of the certification form are only required to be completed once; however, sections C and D must be completed for each permit condition of each emission unit. Deviations from permit conditions must be reported on form E. Please make as many copies of form C, D, and E as necessary.

The federal forms and instructions are located at:

<http://www.epa.gov/oar/oagps/permits/p71forms.html>

The ARMA form for Section III is located at:

www.mde.state.md.us/arma/Programs/Aqcompl/aqcompl.html

Please ensure that your certification is received by ARMA on or before April 1, 2002. Completed forms should be mailed to Mike Melito, Air Quality Compliance Program, 1800 Washington Blvd., Baltimore MD 21230. Failure to meet this deadline is a violation of your Part 70 Permit. A copy of your annual compliance certification must also be sent to the Environmental Protection Agency at the following address:

Associate Director
Office of Enforcement and Permit Review (3AP10)
U.S. EPA Region III
1650 Arch Street
Philadelphia PA 19103-2029

If you have any questions, please call your ARMA contact at 410-537-3231.

Sincerely,

Frank Courtright, Manager
Air Quality Compliance Program
Air and Radiation Management Administration